WO #02-60456-0 AND ALL ASSOCIATED SUBS

MO.NO	Description	Crew No
	(FOR KEN NIELSON) FOR MATERIALS USED	
02-60456-20	UNIT 1 "OVER-FIRE CONTRACTOR COST TRACKER"	81
	(FOR PHIL HAILES) FOR WINDBOX DUCT INSTALLATION	
02-60456-21	INSTALL TEMP. POWER IN THE UNIT TWO BOILER AREA AS	63
	IT WAS IN THE UNIT ONE BOILER FOR THE OVER FIRE	
	AIR PROJECT.	
02-60456-22	RETROFIT BOILER VENT FAN 44 AND DUCT WORK IMPACTED	63
	BY OVERFIRE AIR MODIFICATION	
02-60456-23	UNIT 1 "OVER-FIRE CONTRACTOR COST TRACKER"	81
	(FOR PHIL HAILES) FOR HVAC DUCT RELOCATION	
02-60456-24	RETURN PRINTED OUTPUT BOARD TO FOXBORO	89
	FOR REPAIR/REPLACEMENT.	
02-60456-25	OPEN / CLOSE ACCESS DOORS TO THE NEW OVERFIRE AIR	157
	DUCT FOR INSPECTION DURING MINI-OUTAGE.	
02-60456-26	INSTALL NEW BEARINGS ON THE OVERFIRE AIR DAMPER	157
	SHAFTS. TRACKING WORK ORDER FOR (PHIL HAILES).	
	PIPE / POPPET VALVE FLANGE GASKET REPLACED.	
02-60456-27	FABRICATE 4 ea SLAG HAMMERS PER THE ATTACHED	57
	DRAWING.	
02-60456-28	PROVIDE SCAFFOLD AND INSULATION SERVICES TO REPAIR	97
	DAMAGED AND MISSING INSULATION ON THE SOOTBLOWER	
	DRAINS PIPING.	
02-60456-29	UNIT 1 OVER FIRE AIR, RE-INSTALL CDR 175 JORDAN	57
	DRIVE GEAR BOX.	
02-60456-30	UNIT 1 OVER FIRE AIR, REPLACE THE JORDAN DRIVE FOR	91
	CDR 175.	
02-60456-31	Install Replacement 1/3 OFA Damper Drives.	91
	Commence work after receipt of replacement drives.	
	Will require I&E disconnection of existing	
	drives, mechanical removal of existing drives and	
	mounting of replacement drives, and I&E	
	reconnection of new drives with amplifier line-up.	
	See Ken Nielson or Phil Hailes if questions.	
02-60456-32	INSTALL REPLACEMENT 1/3 OVER FIRE AIR DAMPER	57
	DRIVES PER ENGINEERING REQUEST	
02-60456-33	TEMP. REPAIR BEARINGS ON THE OVERFIRE AIR DAMPER	57
	SHAFTS. TRACKING WORK ORDER FOR (PHIL HAILES).	
	PIPE / POPPET VALVE FLANGE GASKET REPLACED.	

